



# DEFECT ANALYSIS PRODUCTION PROCESS SOLAR STREET LIGHT WITH APPROACH ROOT CAUSE ANALYSIS

Bagus Krisviandik<sup>1)</sup> and <sup>2)</sup>Moses Laksono Singgih

Master's Program in Management of Technology, Institut Teknologi Sepuluh Nopember Jl. Cokroaminoto 12A, Surabaya, 60264, Indonesia e-mail: <sup>1)</sup>andik002@gmail.com and <sup>2)</sup> moseslsinggih@ie.its.ac.id

## ABSTRACTS

PT. Santinilestari Energi Indonesia is a company engaged in renewable energy in the core business of producing street light based on solar cell and smart system. The company's main focus is to meet the needs of consumers by producing products that have good quality. However, various obstacles encountered make the light production quality down, during the period January 2016 to April 2016 there have been recorded Work Order (WO) is done by the production department. For WO Assembly Controller there is a defect by 8.85%, WO Assembly Solar Cell Cable is defect amounted to 8.04%, WO Assembly Reflectors are a defect amounting to 6,23%, and WO Assembly Armature contained 4.79% defect. In order to find and understand the main cause of defects in production there are many methods that can apply, one of the methods is Root Cause Analysis. This research designed to 5 stages that is The Data Collection, The Definition Problems, Finishing Phase Problems, and The Conclusion and Recommendations. The data collection was done by taking secondary data, an interview with the manager production or manager operational, and observation field. Data processing uses method Cause Effect Diagram and FMEA. The purpose of this research is to find and provide solutions the causes of defects in street light product.

Keywords: Root Cause Analysis, SIPOC, FMEA.

### **INTRODUCTION**

PT. SEI is a company engaged in renewable energy with the core business of producing street light based on solar cell and smart system. The company's main focus is to meet the needs of consumers by producing products that have good quality. However, various obstacles encountered make the lights production quality down, during the period January 2016 to April 2016 there have been recorded Work Order (WO) is done by the production department. For WO Assembly Controller there is a defect by 8.85%, WO Assembly Solar Cell Cable are defect amounted to 8.04%, WO Assembly Reflectors are defect amounting to 6,23%, and WO Assembly Armature contained 4.79% defect.

Any business in highly competitive always competes with industry of which a kind of. In order to win the competition, business owners have to pay full attention on the quality of the product. Attention on the quality of giving positive impacts to businesses through two ways namely the effect on production costs and the effect on income. If at the process of production is there are defects due to negligence operators and skill that is not of particular importance for the operators itself, then it obviously will increase production costs.

To find and understand the root cause defect in the production area there are many the methods that can apply, one of method is root cause analysis. Root cause analysis (RCA) is a tool problem solving to help the company find and understand the root of the problem, with the purpose of removing the root cause and prevent problems were back. Basically, RCA





aimed at identifying the origin of a time. With the defective product is required to improve quality by knowing the root cause of problems that arise so as to reduce defects in the production process.

### METHODOLOGY

#### **Root Cause Analysis**

Defects can be defined as a characteristic that does not meet quality standards. Besides the severity of one or more damage to the product can make the product is rejected or disabled (Gaspersz, 2002). Root cause analysis (RCA) used to identify the root cause a time. RCA is a comprehensive evaluation methods structured to identify the root cause (root cause) events that was not expected (undesired outcome) and measures necessary to prevent such back to the that was not expected.

a. SIPOC Diagram

To identify the process that is being studied, in-out and the output of the process, as well as suppliers and customers, it takes a map illustrating the process flow. Tools commonly used is a diagram of SIPOC. SIPOC (Supplier, Input, Process, Output, Customer) used to indicate mainly activity or subprocess in a of business process, together with the framework of the process, which are presented in Supplier, Input, Process, Output, Costumer. SIPOC Model is the most widely used in the management process improvement.




Fig. 1. Portfolio valuation SIPOC (Source: Antony, 2006)

b. Pareto Chart

Diagram Pareto is a tool that used to identify and prioritize based on the order of many problems of a chart stems. Diagram Pareto very useful in determining and identify priorities of the problems that will be completed. The problem most often and often happens is the main priority to do the act of repairing. Diagram Pareto created based on statistics and principle that 20 percent cause, responsible for 80% problems that arise or otherwise.



#### c. Cause and Effect Diagram

Cause and effect diagram is used to analyze the problem and the factors that cause the problem. Thus the diagram can be used to explain the causes of a problem. The figure also called Fishbone diagram because it is shaped like a fish skeleton. The ideas gained from a meeting brainstrorming owned by a group written in a fishbone diagram and then one by one the factors causing that does not become the root causes and eventually started to remove the remaining factors that actually approached the expected goals.




Fig. 2. Example Fishbone (Source: Barsalou, 2015)

d. Failure Mode Effect Analysis

Failure Mode and Effect Analysis (FMEA) is a systematic approach that implements a table method to help the thought process used by engineers to identify potential failure modes and effects. FMEA (Failure Mode and Effect Analysis) is an engineering technique used to identify, prioritize, and dispose of the potential problems of a system, design or process before the failure identified by consumers (Stamatis, 2003).


According to Kennedy (1998), the purpose of the FMEA is as follows:

- 1. Identify potential process failure occurs.
- 2. Finding the impact of a variety of failures.
- 3. Finding the root cause of a failure.
- 4. Prioritize actions to be taken according to the failure rate indicated by the Risk Priority Number (RPN).
- 5. Identify and document recommendations for improvements

#### **Control Plan**


The purpose of the Control Plan is to assist in the manufacturing of quality products according to customer requirements. This is done by providing a structured approach to the design, selection and application of control methods for the value-added system in total. Control Plans provide a written summary description of the system used in the process and minimize product variation.

Control Plan does not replace the information contained in detailed operator instructions. The methodology is applicable to a variety of manufacturing processes and technologies. Control Plan is an integral part of the overall quality and to be used as a living document. Therefore, this section should be used in conjunction with other relevant documents. An important phase of the process for quality planning is the development control plan.






Control Plan is a written description of the system for controlling parts and processes. Single Control Plan may apply to a group or family of products produced by the same process to the same source. In supporting the control plan, process monitoring instructions should be defined and used continuously. Consequently, Control Plan describes the actions required at each stage of the process including receiving, on-process, out-going, and periodic requirements to assure that all process outputs will be in controlled circumstances.



# **RESULTS AND DISCUSSION**



In Figure 1 shows that the first dominant defect in the assembly of the controller or controller module with the presentation of 8.85%, the second flaw is the cable assembly solar cell with a value of 8.04%, the third flaw is a reflector assembly with a value of 6.23%, and disability the fourth is the armature assembly with a value of 4.79%.




Fig. 2. Pareto Defect of Process Ass. Street Lamp

In this study, there are limitations that the experiment in taking corrective action, so that recommendations for improvement are only shown in the table control plan.





# Table 1. FMEA for Process Ass. Street Lamp.

Alf constant     Alf constant     Bio ClaC10 ClaC     9     NA     The initial important process of the disc constant proces of	Proses Funtion/ Requirement	Potential Failure Mode	Potential Effects of Failure	Sev	Potential Cause(s)/ Mechanism(s) of Failure	Occur		rocess Controls evention)	Current Process Controls (Detection)	Detect	RPN	
Abc. controller many enginese controller full enginese controller full enginese controller full account of the barry will control for the barry will control	Ass. Controller	ADC error			Elco C1&C10 Crack		8	N/A	The initial inspection process	3	\$ 19	92
Ass. Controller is not monitored, not intervention of the start of th				8	ADC component tolerances				controller to the data AVO	2	2 14	14
Ass. Controller vall ov the controller vall of the buffer will value of					AVO uncalibrated		9 Ensuring too calibrated be	l has been efore use	each appliance during the	1	1	72
Part of the batches will solve the part of the batches will be batches will batches will bat			commanded, the batteries will swell, the battery will catch fire,				9	N/A	Inspeksi 100% on proses	3	\$ 24	13
Ave. Cable Solar Cell         Control are indication in the control of the out of the module in control of module in control				9	Soket Crack		7	N/A	The initial inspection process	1	\$ 18	39
Codd orf communication n         Controller is not maintelling system in the is owned by the controller         7 Solder Crack         8         N/A         The initial impection process         3         164           Solder results underdone separated         Eastery will not charge the next separated         Solder results underdone         6         N/A         Impects 100% on process         3         144           Ass. Cable schart Cell         Impects 100% on process         3         144         Solder less beat         5         Solder results underdone         6         N/A         Impects 100% on process         3         142           Ass. Cable schart Cell         Impects 100% on process         3         144         Impects 100% on process         3         162           Cable appects 100%         Operator hast         6         N/A         Impects 100% on process         3         163           Ass. Cable         Lamy off         8         Pad on the CB scorosion         7         Provide appectriat cools         1mpects 100% on process         3         163           Ass. Reflector         Lamy off         8         Pad on the CB scorosion         7         PAG         1mpects 100% on process         3         164           Ass. Reflector         LED off         Lamp off         8         Pa								too high the				
communication n     will hole an intelligent system of separated     7 Solde Treack     8     N/A     The initial inspection process     3     165       Soldering th separated     Solder results underdone     6     N/A     Inspectsi 100% on proces     3     165       Axs. Cable     Solder results underdone     6     N/A     Inspectsi 100% on proces     3     165       Axs. Cable     The initial inspection process     3     165     166					Fan curved pin socket		5 When plug socket ascertained in completely		Inspeksi 100% on proses	3	\$ 16	52
Ass. Cable Solder fuely biology of the solution of after 3 days Solder less heat 5 supplied solder reserve 1 the initial inspection process 3 4 d Cable quality is not good 2 N/A The initial inspection process 3 4 d Cable quality is not good 2 N/A The initial inspection process 3 4 d Less scrupulous operators 6 N/A Impecksi 100% on proses 3 1 d The skill of the operator less 6 N/A Impecksi 100% on proses 3 1 d Cable quality is not good 2 N/A Impecksi 100% on proses 3 1 d The skill of the operator less 6 N/A Impecksi 100% on proses 3 1 d Solder results underfore 8 Solder less MA Impecksi 100% on proses 3 1 d The skill of the operator less 6 N/A Impecksi 100% on proses 3 1 d Solder results underfore 6 N/A Impecksi 100% on proses 3 1 d Impecksi 100% on proses 3 1 d Solder results underfore 6 N/A Impecksi 100% on proses 3 1 d Solder results underfore 6 N/A Impecksi 100% on proses 3 1 d Impecksi 100% on proses 3 1 d Impecksi 100% on proses 3 1 d Impecksi 100% on proses 3 1 d Solder results underfore 6 N/A Impecksi 100% on proses 3 1 d Impecksi 10		communicatio	will lose an intelligent system	7	Soket Crack		8	N/A	The initial inspection process	3	\$ 16	58
socket easily hardery win hor after 3 days separated has used of after 3 days separated has used of after 3 days Ass. Cable Solar Cell 		socket easily	Battery will not charge the next lights turn off after 3 days	8	Solder results underdone		6	N/A	Inspeksi 100% on proses	3	3 14	14
Ass. Cable Solar Cell       Cable quilty is not good       3       NA       The initial inspection process       3       144         Solar Cell       Cables peel module       Cable agree of the controller module       Cable agree of the controller module       0       0       0       144       100% on proses       3       162         Procession       Cable agree of the controller module       0       0       0       1       100% on proses       3       162         Procession       Cable agree of the controller       0       0       0       0       1       100% on proses       3       162         Procession       Procession       0       0       0       0       0       1       100% on proses       3       162         Ass. Reflector       Lamp off       8       Pad on the PCB is too small       7       N/A       The initial inspection process       3       162         Ass. Reflector       LED off       Lamp off       8       Pad on the PCB is too small       7       N/A       The initial inspection process       3       162         Ass. Reflector       Lamp off       8       Forme tensile test conducted by the gree of the cub on gree of					Solder less heat		5 Supplied sol	der reserve	The initial inspection process	3	3 12	20
Ass. Cable Solar Cell       The skill of the operator less       6       N/A       Inspeksi 100% on process       3       162         Solar Cell       Cause a surge in the controller module       Operator baste       6       N/A       Inspeksi 100% on process       3       162         Operator baste       Operator baste       5       Povide appropriate tools to process       7       N/A       Inspeksi 100% on process       3       13         Solder results underdone       6       N/A       Inspeksi 100% on process       3       14         Solder results underdone       6       N/A       Inspeksi 100% on process       3       14         Ass. Reflector       Lamp off       8       Pad on the PCB icrossion       7       Earn cleaning process       3       16         Ass. Reflector       LED off       Lamp off       8       Pad on the PCB icrossion       7       N/A       The initial inspection process       3       16         Ass. Reflector       LED off       Lamp off       8       Former tensile test conducted by the supplier       Solder result       Solder result       Solder result       3       162         Ass. Armature       Controller       Lamp off       8       Former tensile test conducted by the supplier       N/A					Tin quality is not good		2	N/A	The initial inspection process	3	<b>;</b> 2	18
Solar Cell     Less serupalous operators     6     N/A     Impecks 100% on process     3     162       cables ped module     Cause a surge in the controller module     P     Operator haste     6     N/A     Impecks 100% on process     3     162       Solar Cell     The tools used are not appropriate process     5     Provide appropriate tools of Lamm Photore starting the process     The initial inspection process     3     162       Ass. Reflector     Lamp off     8     Pad on the PCB corronion     7     Extra Lemma process     3     162       Ass. Reflector     LED off     Lamp off     8     Pad on the PCB is too small     7     N/A     The initial inspection process     3     162       LED off     Lamp off     8     Former tensile test conducted by the group lier     5     N/A     Inspecksi 100% on proses     3     162       Solder the LED underdone     5     N/A     The initial inspection process     3     122       Solder the LED underdone     5     N/A     Inspecksi 100% on proses     3     124       Solder the LED underdone     5     N/A     Inspecki 100% on proses     3     124       Solder the LED underdone     5     N/A     Inspecki 100% on proses     3     124       Solder the LED underdone												
cubics peel     Cause a surge in the controller module     9 0perator haste     6     N/A     Impecksi 100% on process     3     162       9 0perator haste     9 0perator haste     6     N/A     Impecksi 100% on process     3     132       100000     10000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     1000000     10000000     1000000     1000000     10000000     10000000     10000000     10000000     1000000000     100000000000     100000000000000000000000000												
cables ped module       Cause a sarge in the controller module       9       1       The tools used are not appropriate Sanding wrong way       5       Provide appropriate tools Learn Wi before starting the process       Inspecks 100% on proses       3       13         Inspecks       Iows and propriate       5       N/A       Inspecks 100% on proses       3       142         Ass. Reflector       8       Pad on the PCB corrosion       7       Extra cleaning process with The initial inspection process       3       162         Ass. Reflector       9       Aas       Pad on the PCB is too small       7       N/A       The initial inspection process       3       162         LED off       Lamp off       8       Pad on the PCB is too small       7       N/A       The initial inspection process       3       162         LED off       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       142         fail       Controller fail       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       Inspecks 100% on proses       3       142         fail       Controller       Lamp off       8       Not yet a Zener Diode soldered fail       6       N/A       Inspecks	Solar Cell				Less scrupulous operators		0	N/A	inspeksi 100% on proses	2	10	»Z
Ass. Reflector       Solder results underdone       Solder results underdone       NA       Impose 100% on process       3       13         Ass. Reflector       Solder results underdone       Solder results underdone       Supplied solder reserve       Fatta (Beinging process)       The initial inspection process       3       142         Ass. Reflector       PCB pad       The initial inspection process       3       162         LED off       Lamp off       8       Pad on the PCB is too small       7       NA       The initial inspection process       3       162         LED off       Lamp off       8       Former tensile test conducted by the souther on track too high LED       Sander network too high LED       Sampling on process       3       122         Controller       Lamp off       8       Former tensile test conducted by the souther on track too high LED       Sampling on process       3       122         Solder results underdone       6       NA       Imspecksi 100% on process       3       124         fail       Lamp off       8       Former tensile test conducted by the souther on too on task too high LED       Sampling on process       3       124         fail       Golder neet LED underdone       6       NA       Imspecksi 100% on proces       3       124		cables peel		9	Operator haste		6	N/A	Inspeksi 100% on proses	3	3 16	52
Solder results underdone     6     N/A     Inspeksi 100% on proces     3     142       Ass. Reflector     Solder kurang panas     5     Supplied solder reserve     The initial inspection process     3     163       Ass. Reflector     Pad on the PCB corrosion     7     N/A     The initial inspection process     3     164       Ass. Reflector     Image Signation     7     N/A     The initial inspection process     3     164       LED off     Lamp off     8     Pad on the PCB is too small     7     N/A     The initial inspection process     3     162       LED off     Lamp off     8     Former tensile test conducted by the supplier     5     N/A     The initial inspection process     3     122       Solder results underdone     5     N/A     Inspeksi 100% on proses     3     122       Solder results underdone     5     N/A     Inspeksi 100% on proses     3     122       Solder results underdone     6     N/A     Inspeksi 100% on proses     3     124       Gontroller     Lamp off     8     Not yet a Zene Diode soldered     6     N/A     Inspeksi 100% on proses     3     124       Gould not     Controller is not monitored, so it communicati will lose an intelligent system     7     7     124					The tools used are not appropriate		5 Provide app	ropriate tools				
sose cable       Lamp off       8       Pad on the PCB corrosion       7       N/A       The initial inspection process       3       160         Ass. Reflector       -       -       Pad on the PCB is too small       7       N/A       The initial inspection process       3       160         Ass. Reflector       -       -       -       Pad on the PCB is too small       7       N/A       The initial inspection process       3       160         LED off       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       120         Solder resurts       - <td> </td> <td>Sanding wrong way</td> <td></td> <td>6 process</td> <td>fore starting the</td> <td>Inspeksi 100% on proses</td> <td>3</td> <td>\$ 16</td> <td>52</td>					Sanding wrong way		6 process	fore starting the	Inspeksi 100% on proses	3	\$ 16	52
Ass. Reflector       Pad on the PCB is too small       7       N/A       The initial inspection process       3       64         Ass. Reflector       Image: Controller on the PCB is too small       7       N/A       The initial inspection process       3       64         LED off       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       162         Controller fail       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       122         Controller fail       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       Inspectsi 100% on process       3       142         fail       Lamp off       8       Not yet a Zener Diode soldered       6       N/A       Inspectsi 100% on process       3       144         quality of part regulator not good       9       N/A       Inspectsi 100% on process       3       122         Missing setting RF       6       N/A       Inspectsi 100% on process       3       124         fail       Could not       Controller is not monitored, soi t       Interference between RF       9       Checker order not       Inspecksi 100%		loose cable	Lamp off	8			5 Supplied sol	der reserve				
Ass. Reflector       Pid on the PCB is too small       7       N/A       The initial inspection process       3       48         Ass. Reflector       LED off       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       12         Reflector       Controller       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       124         Solder the LED underdone       5       N/A       The initial inspection process       3       124         Solder the LED underdone       6       N/A       Inspecksi 100% on proses       3       144         Not yet a Zener Diode soldered       6       N/A       Inspecksi 100% on proses       3       144         Teminal of pin ort yet soldered       6       N/A       Inspecksi 100% on proses       3       144         Missing setting RF       6       RF Chamel RF       Inspecksi 100% on proses       3       124         Ass. Armature       Could not controller is not monitored, so it communicati will lose an intelligent system that is owned by the controller       7       Interference between RF       0       Checker order not simultaneously while checking       Inspecksi 100% on proses       3	Ass. Reflector				Pad on the PCB corrosion		7 PCB pad	ng process with	The initial inspection process	3	3 16	58
LED off       Lamp off       B       Former tensile test conducted by the supplier       Sampling on process       2       9         LED off       Lamp off       B       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       120         Solder the LED underdone       6       N/A       Inspeksi 100% on proces       3       144         Not yet a Zener Diode soldered       6       N/A       Inspeksi 100% on proces       3       144         The battery will of part regulator not good       9       N/A       Inspeksi 100% on proces       3       120         Missing setting RF       6       N/A       Inspeksi 100% on proces       3       120         Missing setting RF       6       N/A       Inspeksi 100% on proces       3       120         Missing setting RF       6       N/A       Inspeksi 100% on proces       3       120         Missing setting RF and Base station       6       carries a map of the instalfation       Inspeksi 100% on proces       3       120         Ass. Armature       Controller is not monitored, so it on that is owned by the controller       nereference between RF       9       Checker order not simultaneously while checking instalfation       Inspeksi 100% on proces       3       1							7					
LED off       Lamp off       8       Former tensile test conducted by the supplier       5       N/A       The initial inspection process       3       120         Solder results underdone       6       N/A       Inspeksi 100% on proses       3       144         fail       Lamp off       8       Former tensile test conducted by the supplier       6       N/A       Inspeksi 100% on proses       3       144         fail       Lamp off       8       Forminal 6 pin not yet soldered       6       N/A       Inspeksi 100% on proses       3       144         Missing setting RF       When setting a table reading R       Inspeksi 100% on proses       3       120         Missing setting RF       Missing setting RF       When setting the controller       Inspeksi 100% on proses       3       120         Ass. Armature       Outld not controller is not monitored, so it to solered by the controller       Interference between RF       9       Checker order not simultation       Inspeksi 100% on proses       3       126         Ass. Armature       Na       Former tensile will be controller       7       Interference between RF       9       Checker order not simultaneously while checking       186       Simultaneously while checking       186       Simultaneously while checking       186       Simultaneously while c								too high LED		2	<u>,</u>	<del>)</del> 6
Solder the LED underdone       5       N/A       Inspeksi 100% on proses       3       120         Solder results underdone       6       N/A       Inspeksi 100% on proses       3       144         fail       Lamp off       8       Solder results underdone       6       N/A       Inspeksi 100% on proses       3       144         fail       Not yet a Zener Diode soldered       6       N/A       Inspeksi 100% on proses       3       144         Quality of part regulator not good       9       N/A       Inspeksi 100% on proses       3       144         Quality of part regulator not good       9       N/A       Inspeksi 100% on proses       3       126         Missing setting RF       6       RF channel RF       When setting table reading inspeksi 100% on proses       3       126         Missing setting RF       7       Interference between RF       9       Channel divide between       9       Inspeksi 100% on proses       3       185         Ass. Armature       on       that is owned by the controller       7       Interference between RF       9       Checker order not simultaneously while checking       185       185         Fail       Fail       RF fail       S       Before ignited supply in the first check pin-pin RF       <		LED off	Lamp off		Former tensile test conducted by the			N/A		3	3 12	20
Controller failLamp off8Not yet a Zener Diode soldered Terminal 6 pin not yet soldered Quality of part regulator not good6N/AInspeksi 100% on proses Inspeksi 100% on proses3144Ass. ArmatureCould not communicati onController is not monitored, so it will lose an intelligent system that is owned by the controller7Not yet a Zener Diode soldered Terminal 6 pin not yet soldered Quality of part regulator not good Missing setting RF6N/AInspeksi 100% on proses (RF Channel RF When setting the controller (Barrisal Lation)3126Ass. ArmatureCould not communicati onController is not monitored, so it will lose an intelligent system that is owned by the controller7Interference between RF9Channel divide between 9Inspeksi 100% on proses3126Ass. ArmatureThe battery will swell, the battery will catch fire, damage controller7Missed assembly Resistor When mounting resistor foot shot with other components5Before ignited supply in the first check pin-pin RFInspeksi 100% on proses3105Fan failThe battery will swell, the battery will catch fire, damage controller9Missed assembly Resistor The quality of Fan Ugly4N/AInspeksi 100% on proses3105Before ignited supply in the first check pin-pin RFInspeksi 100% on proses3105106Fan failThe battery will catch fire, damage controller9Missed assembly Resistor The quality of Fan Ugly4N/AInspeksi 100% o					**		5	N/A	Inspeksi 100% on proses	3	3 12	20
failLamp ort8Terminal 6 pin not yet soldered Quality of part regulator not good6N/AInspeksi 100% on proses3144Ass. ArmatureCould not communicatiController is not monitored, so it will lose an intelligent system onMissing setting RF6N/AInspeksi 100% on proses3126Ass. ArmatureCould not controller is not monitored, so it romThe battery will swell, the battery will catch fire, damage controllerFan failThe battery will swell, the battery will catch fire, damage controller9N/AInspeksi 100% on proses3126Fan failThe battery will swell, the battery will catch fire, damage controller9N/AInspeksi 100% on proses3105Fan failThe battery will catch fire, damage controller9N/AInspeksi 100% on proses3105Fan failThe battery will swell, the battery will catch fire, damage controller9N/AInspeksi 100% on proses3105Fan failThe battery will swell, the battery will catch fire, damage controller9N/AInspeksi 100% on proses3105Fan failThe battery will swell, the battery will catch fire, damage controller9Pan Logy4N/AInspeksi 100% on proses3105Fan failThe battery will catch fire, damage controller9Pan Logy6N/AInspeksi 100% on proses3105Fan failThe battery will catch fire, damage controller9			Controller is not monitored, so it is will lose an intelligent system	8					1 1			
Ass. Armature       Could not       Controller is not monitored, so it communicati will lose an intelligent system on       7       Missed assembly Resistor       4       N/A       Inspeksi 100% on proses       3       126         Ass. Armature       Fan fail       The battery will swell, the battery will catch fire, damage controller       9       N/A       Inspeksi 100% on proses       3       126         Fan fail       The battery will swell, the controller       9       N/A       Inspeksi 100% on proses       3       126         Fan fail       The battery will swell, the controller       9       N/A       Inspeksi 100% on proses       3       105         Fan fail       The battery will swell, the battery will catch fire, damage controller       9       N/A       Inspeksi 100% on proses       3       105         Fan fail       The battery will swell, the battery will swell, the battery will catch fire, damage controller       9       N/A       Inspeksi 100% on proses       3       105         Fan fail       The battery will swell, the battery will catch fire, damage controller       9       N/A       Inspeksi 100% on proses       3       105         Hard So Controller       Fan fail       The battery will swell, the battery will catch fire, damage controller       9       N/A       Inspeksi 100% on proses       3       105												
Could not controller is not monitored, so it communicati will lose an intelligent system on that is owned by the controller       Missing setting RF       6 When setting a table reading RF Channel RF When setting the controller       Inspeksi 100% on proses       3 126         Ass. Armature       Could not controller is not monitored, so it communicati will lose an intelligent system on that is owned by the controller       7       Interference between RF       9 Checker order not simultaneously while checking       Inspeksi 100% on proses       3 185         Ass. Armature       N       The battery will swell, the battery will swell, the battery will catch fire, damage controller       9       Missed assembly Resistor When mounting resistor foot shot with other components       4       N/A       Inspeksi 100% on proses       3 105         Fan fail       The battery will swell, the battery will catch fire, damage controller       9       The quality of Fan Ugly       6       N/A       Inspeksi 100% on proses       3 105	Ass. Armature				1 5		6 0					
Ass. Armature       Could not       Controller is not monitored, so it communicati will lose an intelligent system on that is owned by the controller       Nissing setting RF and Base station       6 arries a map of the inspeksi 100% on proses       3 126         Ass. Armature       Could not       Controller is not monitored, so it communicati will lose an intelligent system on that is owned by the controller       7       Interference between RF       9 Checker order not simultaneously while checking       1 lospeksi 100% on proses       3 185         Ass. Armature       The battery will swell, the Fan fail       The battery will swell, the battery will swell, the fan fail       Missed assembly Resistor when mounting resistor foot shot with other components       3 The accuracy when mounting Resisti 100% on proses       3 105         Fan fail       The battery will swell, the controller       9       The quality of Fan Ugly       6       N/A       Inspeksi 100% on proses       3 105							When setting		1 1			
Could not controller is not monitored, so it communicati will lose an intelligent system on that is owned by the controller       7       Interference between RF       9       Checker order not simultaneously while checking       Inspeksi 100% on proses       3       185         Ass. Armature       on       that is owned by the controller       7       RF fail       5       Before ignited supply in the first check pin-pin RF       Inspeksi 100% on proses       3       105         Fan fail       The battery will swell, the battery will catch fire, damage controller       9       The quality of Fan Ugly       6       N/A       Inspeksi 100% on proses       3       162		communicati					<sup>6</sup> RF Channel When setting	RF g the controller				
Ass. Armature       Could not communication will lose an intelligent system that is owned by the controller       7       Interference between RF       9 Checker order not simultaneously while checking       Interference between RF       9 Checker order not simultaneously while checking       Interference between RF       9 Checker order not simultaneously while checking       18         Ass. Armature       RF fail       RF fail       Before ignited supply in the first check pin-pin RF       Inspeksi 100% on proses       3       105         Fan fail       The battery will swell, the battery will catch fire, damage controller       9       Missed assembly Resistor the quality of Fan Ugly       4       N/A       Inspeksi 100% on proses       3       105         Fan fail       The battery will catch fire, damage controller       9       The quality of Fan Ugly       6       N/A       Inspeksi 100% on proses       3       162					Missing setting RF and Base station		installation		inspects 100% on proses	2	i 12	26
Missed assembly Resistor       4       N/A       Inspeksi 100% on proses       3       108         Missed assembly Resistor       4       N/A       Inspeksi 100% on proses       3       108         The battery will swell, the       other components       3       The accuracy when mounting Resistor       108       Inspeksi 100% on proses       3       81         Fan fail       battery will catch fire, damage controller       9       The quality of Fan Ugly       6       N/A       Inspeksi 100% on proses       3       162					Interference between RF		9 Checker order not		Inspeksi 100% on proses	3	5 18	39
The battery will swell, the Fan failWhen mounting resistor foot shot with other components3 The accuracy when mounting ResistorInspeksi 100% on proses3 81Fan failbattery will catch fire, damage controller9 The quality of Fan Ugly6N/AInspeksi 100% on proses3 162					RF fail		5 Before ignite first check p	ed supply in the in-pin RF	Inspeksi 100% on proses	3	3 10	)5
The battery will swell, the     other components     5 Resistor     Inspeksi 100% on proses     5 8 1       Fan fail     battery will catch fire, damage     9 The quality of Fan Ugly     6     N/A     Inspeksi 100% on proses     3 162       controller     6     N/A     Inspeksi 100% on proses     3 162		Fan fail	battery will catch fire, damage						Inspeksi 100% on proses	3	3 1(	)8
Fan fail         battery will catch fire, damage         9         The quality of Fan Ugly         6         N/A         Inspeksi 100% on proses         3         162           controller         controller </td <td></td> <td colspan="2">•</td> <td></td> <td>y when mounting</td> <td>Inspeksi 100% on proses</td> <td>3</td> <td>3 8</td> <td>31</td>					•			y when mounting	Inspeksi 100% on proses	3	3 8	31
				9				N/A	* *			
The quality of the Regulator Ugly 6 N/A Inspeksi 100% on proses 3 162					The quality of the Regulator Ugly		6	N/A	Inspeksi 100% on proses	3	3 16	52





#### **CONCLUSIONS AND RECOMMENDATIONS**

Recommended improvements gained by doing brainstorming with better understand the issues section Production and Quality Control in the field. Based on the results of FMEA and priorities known risk, then in order to maximize the reduction in the number of defects in the product up to zero defect level to do some proposals as follows:

- a. Personnel: Conduct training about basic electronics (Soldering, reading electronic components). Selection at recruitment provider with which own Basic electronics.
- b. Machines: Doing eye replacement of solder or heater Solder itself.
- c. Methods: Make changes by checking (division RF channel) are previous 1 RF channel is done by some inspector, became one RF channel is held by 1 Inspector check.
- d. Material: Selecting and evaluating the performance of suppliers so obtained a supplier with a good performance.
- e. Measurement: Buying a calibration tool for calibrating AVO meter.

#### REFERENCES

Antony J. et al. (2006), World Class Applications of Six Sigma. Elsevier, India

- Barsalou Matthew A. (2015), *Root Cause Analysis: A Step by Step Guide to Using the Right Tool at The Right Time*. CRC Press, Boca Raton.
- Elean.A.Y.W. and Moses Laksono Singgih, 2015, PERBAIKAN PROSES PRODUKSI GULA AREN DENGAN PENDEKATAN LEAN MANUFACTURING DI PABRIK GULA AREN MASARANG TOMOHON, Prosiding Seminar Nasional Manajemen Teknologi XXIII, Surabaya 1 Agustus 2015.
- Gaspersz Vincent. (2002), Pedoman Implementasi Six Sigma Terintegrasi dengan ISO 9001:2000, MBNQA dan HACCP, PT. Gramedia Pustaka Utama, Jakarta.
- Kennedy, M. (1998). Failure modes & effects analysis (FMEA) of flip chip devices attached to printed wiring boards (PWB). *IEEE PMT International Electronics Manufacturing Technology Symposium*.
- Moses Laksono Singgih, and Renanda, 2008, **Peningkatan Kualitas Produk Kertas Dengan Menggunakan Pendekatan Six Sigma di Pabrik Kertas Y**, Seminar Teknosim 2008, ISSN: 1978-6522, Jurusan Teknik Mesin dan Teknik Industri – Fakultas Teknologi – Universitas Gajah Mada Yogyakarta, Universitas Gajah Mada Yogyakarta, 16 Oktober 2008.
- Pramitasari.L.M. and Moses Laksono Singgih, 2015, DETEKSI FALSE ALARM MENGGUNAKAN RESIDUAL CONTROL CHART BERDASARKAN METODE SUPPORT VECTOR REGRESSION, Prosiding Seminar Nasional Manajemen Teknologi XXIII. Surabaya, 1 Agustus 2015.
- Stamatis, D.H. (2003), *Failure Mode and Effect Analysis: FMEA from Theory to Execution*. ASQ Quality Press, Milwaukee Wisconsin.
- Wicaksono, I.K dan Moses Laksono Singgih, 2011, Manajemen Risiko K3 (Keselamatan Dan Kesehatan Kerja) Pada Proyek Pembangunan Apartemen Puncak Permai





Surabaya, Prosiding Seminar Nasional Manajemen Teknologi XIII Program Studi MMT-ITS, Surabaya 5 Pebruari 2011.